

KCACR BELL RESTORATION WORKS

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO> OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
ADDINGTON	REHUNG IN NEW FRAME 1969		1	0	1970	21	350		
ADISHAM	BELLS REMOVED FROM FRAME AND STORED		1	1,000		0		3	
ALDINGTON	VARIOUS MAINTENANCE		1	500		0			
ALKHAM	VARIOUS MAINTENANCE		1	500		0			
APPLEDORE	BELLS REHUNG WITH NEW BEARINGS OLD FITTINGS		1	2,000	1969	17	265		
APPLEDORE					1989	800	2,160		
ASH BY SANDWICH	BELLS REHUNG AUGMENTED TO 10, NEW FRAME FITTINGS		1	4,000	1978	?		8	
ASH BY WROTHAM	BELLS REHUNG IN EXISTING FRAME, NEW FITTINGS		1	4,000	2010	6,000	8,114	6	
ASHFORD	BELLS REHUNG AUGMENTED TO 10, NEW FRAME FITTINGS		1	4,000	1965	30	407		
					1970	10	166		
					2007	500	730		
AYLESFORD	FRONT FIVE REMOVED/REHUNG NEW FITTINGS (KCACR)		1	6,000	2005	4,000	6,200	5	
					1979	100	580		
					1982	300	1,162		
BADDLESMERE	VARIOUS MAINTENANCE		1		1987	100	293		1
BARHAM	VARIOUS MAINTENANCE ALTERATIONS RE GALLERY		1	2,000	2004	?			
BARMING	REMOVE BELLS BELLS REHUNG NEW FITTINGS, EXISTING FRAME		1	5,000	2014	9,000	10,404	6	
					1951	10	345		
BEARSTED	BELLS REHUNG		1		1975	125	1,059	1	
	5TH REMOVED FOR WELDING			3,000	1993	300	626		
	2ND REHUNG BROKEN GUDGEON			2,000	2013	0	0		
	TENOR QUARTER TURNED			2,000	2018	0	0		
BECKENHAM					1992	3,500	7,578		
					1952	15	475		
BEKESBOURNE	REMOVE BELLS BELLS REHUNG NEW FITTINGS, EXISTING FRAME		1	5,000	2005	4,000	6,193	6	
BENENDEN	BELLS REHUNG IN NEW FRAME AND FITTINGS		1		1971	35	547		
	AUGMENTED TO 13				2003	1,000	1,595		
BETHERSDEN	VARIOUS MAINTENANCE		1	2,000		0			

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
BETTESHANGER	VARIOUS MAINTENANCE		1	500		0			
BEXLEY	KCACR REHANG IN EXISTING FRAME REMOVE 4TH FOR RECASTING		1	4,000	1938	500	797	8	
					1999				
					2003				
					1956	5	132		
BICKLEY	OLD 5 REMOVED KCACR NEW 8 IN NEW FRAME FITTINGS		1	3,000	1991	3,000	6,878	5	
	2 TREBLES ADDED				1993				
BICKNOR	VARIOUS MAINTENANCE INSPECTION KCACR		1	500		0			
BIDDENDEN	VARIOUS MAINTENANCE		1	500		0			
BIGGIN HILL	VARIOUS MAINTENANCE		1	500	1980	50	255		
BILSINGTON	VARIOUS MAINTENANCE		1	500		0			1
BIRCHINGTON	VARIOUS MAINTENANCE INSPECTION		1	200		0			
BIRLING	BELLS REMOVED KCACR		1	4,000	1986	2,000	6,118	8	
	BELLS REHUNGS NEW FRAME SOME RECAST								
BISHOPSBOURNE	REHUNG AS A CHIME EXTRA BELL KCACR		1	3,000	1975	0			
BLACKHEATH	INSPECTION RE POSSIBLE NEW INSTALLATION		1	80		0			1
BOBBING	VARIOUS MAINTENANCE REHUNG 1935		1	800	1935	5	360		
BONNINGTON	VARIOUS MAINTENANCE		1	500		0			1
BORDEN	VARIOUS MAINTENANCE		1	1,000		0			
BOUGHTON UNDER BLEAN	BELLS REMOVED KCACR REHUNG EXISTING FRAME N/F		1		1979	250	1,450	8	
	7TH RECAST			3,000	2003	4,000	6,379		
BOUGHTON MONCHELSEA	BELLS REMOVED REHUNG NEW FITTINGS OLD FRAME		1	6,000	1992	4,500	9,745	6	
	NEW GUIDE INSTALLED	KCACR							
BOXLEY	VARIOUS MAINTENANCE		1	1,500		0			
BRABOURNE	REHUNG NEW FRAME FITTINGS AUGMENTED TO 8		1	?	1966	20	390		
					2002				
BRASTED	BELLS REMOVED KCACR				1988	450	1,278	6	
	REHUNG IN EXISTING FRAME NEW FITTINGS AUGMENTED TO 8		1	6,000	2005	4,000	6,193		
BREDGAR	BELLS REHUNG AND AUGMENTED TO 6 NEW FRAME FITTINGS		1	?	1967	25	470		

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
BREDHURST	2 BELLS HUNG FOR SWING CHIMING	KCACR	1	2,000				2	1
BRENCHLEY	VARIOUS MAINTENANCE		1	2,000		?			
BRENZETT	VARIOUS MAINTENANCE		1	500		0			
BRIDGE	INSPECTION RE POSSIBLE NEW INSTALLATION		1	80		0			
BROADSTAIRS	SOLENOID FITTED TO SINGLE BELL	TAYLORS	1		2019	0			1
BROMLEY ss PETER PAUL	NEW GUDGEON ON 6TH?	TAYLORS	1		2019	0			
					1952	10	316		
BROOK	REHUNG DEAD IN VERY OLD FRAME	W/C	1	?		0			
BROOKLAND	BELLS / FRAME REMOVED KCACR REHUNG IN NEW FRAME		1	6,000	1973	0		5	
	FITTINGS AND AUGMENTED TO 6					?			
BROOMFIELD	BELLS REHUNG IN EXISTING FRAME, NEW FITTINGS		1		2015			6	
	NEW FRAME BUILT LOCALLY FOR 3 NEW BELLS			10,000		10,000			
BUCKLAND BY DOVER	BELLS AUGMENTED TO 6 BELL CHIME		1			0			
BURHAM	BELLS REMOVED FROM NEW CHURCH FOR USE ELSEWHERE KCACR		1	2,000		0		3	
BURMARSH	VARIOUS MAINTENANCE			3,000	1966+	0			
CANTERBURY CATHEDRAL	BELLS RECAST/REHUNG/AUGMENTED TO 14	W/C	1		1981	?			
CANTERBURY HOLY CROSS	BELLS REMOVED FOR USE AT WESTGATE	KCACR	1	3,000	1972	22	314	5	
CANTERBURY ST ALPHEGE	VARIOUS WORKS	KCACR	1	3,000		0			
CANTERBURY ST DUNSTAN	VARIOUS WORKS	KCACR	1	3,000	2017	2,500	2,745		
CANTERBURY ST GREGORY	THE 3 BELLS REMOVED FOR WORMSHILL	KCACR	1	2,000		?		3	
CANTERBURY ST MARGARET	THE 3 BELLS REMOVED FOR USE ELSEWHERE		1			0		3	
CANTERBURY ST PAUL	TENOR RECAST HUNG FOR SWING CHIMING KCACR		1	3,000	1987	100	1,427		
CANTERBURY ST PETER	AUGMENTED TO 4 HUNG DEAD	KCACR	1			0			
CANTERBURY ST STEPHEN	BELLS REMOVED AND REHUNG SOME RECAST				1971	21	328		
	EXISTING FRAME	KCACR	1	6,000		0			
CHALK	BELLS REMOVED	KCACR			1998			3	
	REHUNG / AUGMENTED NEW FRAME	W/C	1	3,000		2,000	3,700		
CHARING	BELLS REMOVED	KCACR		3,000	1992	3,700	8,011	6	
	REHUNG RETUNED	JT							

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
CHART SUTTON	REHUNG IN EXISTING FRAME TUNED	W/C	1	0	1967	0			
CHARTHAM	VARIOUS MAINTENANCE	KCACR	1	2,000		?			
CHATHAM	BELLS REMOVED FOR USE AT ST GORAN	KCACR	1	2,000	2014	0		8	
CHATHAM ALL SAINTS	REPAIRS TO TUBULAR BELLS	KCACR	1	200		0			
CHELSFIELD	BELLS REMOVED	KCACR	1	3,000	1993	1,700	3,550	5	
	REHUNG AND AUGMENTED TO 8	JT			2009	?			
CHERITON ALL SOULS	NEW CLAPPER FITTED TO SINGLE BELL	KCACR	1	500					
CHERITON ST MARTIN	REHUNG / TUNED JT	KCACR	1	6,000	2011	6,000	7,756	8	
					1964	20	423		
CHEVENING	2 ORIGINAL BELLS REMOVED ASSISTANCE	KCACR		5,000		?		2	
	REHUNGAUGMENTED TO 8	W/C	1		99/07				
CHIDDINGSTONE	REHUNG TUNED ASSISTANCE	W/C	1	5,000	1991	3,000	6,879	8	
CHILHAM	TENOR REPLACED VARIOUS MAINTENANCE	KCACR	1	4,000	96/18	1,516	1,516	2	
CHILLENDEEN	VARIOUS MAINTENANCE	KCACR	1	200	?				1
CHISLETT	REHUNG TUNED 4TH RECAST 4TH RECAST W/C	JT	1		1959	10	156		
					1971				
					1993	150	313		
CLIFFE AT HOO	BELLS REMOVED	KCACR	1	3,000	2006	4,000	6,025	8	
	REHUNG TUNED IN EXISTING FRAME	JT			1960	5	118		
					1976	80	678		
COBHAM	BELLS REMOVED	KCACR	1	3,000	1994	6,000	12,330	6	
	REHUNG TUNED NEW FRAME FITTINGS	W/C							
COOLING	INSPECTION NO WORK DONE	KCACR	1	80		0			
COWDEN	BELLS AND FRAME REMOVED	KCACR	1	3,000	1997	2,000	3,788	6	
	REHUNG TUNED IN EXISTING FRAME LOWER	W/C			2000				
CRANBROOK	REHUNG TUNED EXISTING FRAME ?	JT	1		1971	22	314		
CRAYFORD	VARIOUS MAINTENANCE		1		1987	550	7,849		
CRAY ST MARY	INSPECTION OF 3 BELLS	KCACR	1	80					
CRUNDALE	TENOR MADE RINGABLE FOR FUNERAL	KCACR	1	200		0			

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
CUDHAM	VARIOUS MAINTENANCE	KCACR	1	500	1970	5	83		
CUXTON			1		1964	20	423		
DARTFORD	VARIOUS MAINTENANCE	KCACR	1	1,000	1992	500	1,082		
DAVINGTON PRIORY	INSPECTION	KCACR	1	80		0			
DEAL	VARIOUS MAINTENANCE	KCACR	1	2,000	1951	10	345		
DEAL ST ANDREW	INSPECTION RE POSSIBLE NEW INSTALLATION	KCACR	1	80		0			1
DENTON	VARIOUS MAINTENANCE	KCACR	1	500		0			1
DETLING	VARIOUS MAINTENANCE	KCACR	1	200		0			1
DITTON	3 BELLS MADE RINGABLE	KCACR	1	1,500		0			
DODDINGTON	INSPECTION OF 2 BELLS	KCACR	1	80		0			1
DOVER ST MARY	BELLS AND FRAME REMOVED ASSISTANCE	KCACR	1	5,000	2001	3,000	5,006	8	
	REHUNG TUNED NEW FRAME FITTINGS	WHITES	1						
DOVER TOWN HALL	THE ZEEBRUGGE BELL REHUNG	BGB/JT	1	0		0		1	1
DOWNE	VARIOUS MAINTENANCE	KCACR	1	2,000	2015	1,000	1,129		
	REHANG 4 5 6 ON NEW BEARINGS	JT			2002	200	333		
						300	500		
DYMCHURCH	TREBLE REOVED FOR WELDING AND REPLACED	KCACR	1	2,000				1	
EAST FARLEIGH	VARIOUS MAINTENANCE	KCACR	1	3,000	1979	1,000	5,796		
	REHUNGAND AUGMENTED TO 8				1955	20	553		
	VARIOUS MAINTENANCE	WHITES			2013	300	357		
EAST LANGDON	VARIOUS MAINTENANCE	KCACR	1	500		0			
EAST MALLING	BELLS REHUNG IN NEW FRAME	KCACR	1		1966	25	48		
	VARIOUS MAINTENANCE	W/C		2,000	1996				
EASTCHURCH	BELLS REMOVED REHUNG TUNED EXISTING FRAME	KCACR	1	6,000	2005	4,000	6,193	6	
EAST PECKHAM	VARIOUS MAINTENANCE	KCACR	1	2,000		0			
EAST SUTTON	REHUNG IN EXISTING FRAME	W/C	1		1983	750	2674		
EASTLING	VARIOUS SITE MEETINGS	KCACR	1	240		0			
EASTRY	BELLS REMOVED REHUNG TUNED EXISTING FRAME	KCACR	1	6,000	2007	4,000	5,838	8	
	AUGMENTED ADDDITIONAL FRAME	M HIGBY			1976	159	1,346		

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
EDENBRIDGE	5 REHUNG IN EXISTING FRAME				1969	11	192		
EGERTON	VARIOUS MAINTENANCE	KCACR	1	1,000		0			
ELHAM	BELLS RECAST REHUNG EXISTING FRAME	W/C	1		1971	39	608		
ELMSTED	INSPECTIONS CHIMES FITTED	KCACR	1	1,000		0			
ELMSTONE	VARIOUS MAINTENANCE	KCACR	1	200		0			
ERITH CHRIST CHURCH	REHUNG WITH LOCAL LABOUR	KCACR	1	3,000		?			
ERITH ST JOHN	REHUNG 1925	W/C			1925	10	316		
					1952				
EYTHORNE	VARIOUS MAINTENANCE	KCACR	1	1,000	1983	500	1,782		
EYNSFORD			1		1974	38	464		
FAIRFIELD	VARIOUS MAINTENANCE	KCACR	1	500		0			
FARNBOROUGH	NEW 6 INSTALLED	KCACR	1	1,000	2011	10,000	12,927	1	
	NEW 6 TO BECOME 8 4TH REMOVED	JT			2020	4,500	4,500		
FARNINGHAM	BELLS REMOVED	KCACR	1	3,000	2008	5,000	6,996	6	
	REHUNG IN EXISTING FRAM RETUNED	W/C							
FAVERSHAM	VARIOUS MAINTENANCE	KCACR	1	2,000				8	
	REHANG AND AUGMENTATION	JT			2020	7,500	7,500		
FAWKHAM	VARIOUS MAINTENANCE PR	KCACR	1	500					1
FOLKESTONE	VARIOUS MAINTENANCE	KCACR	1	500	2018				
	BELLS REHUNG IN EXISTING FRAME, NEW FITTINGS	LOCAL/KCACR		4,000	1976	98	830		
FOLKESTONE ST AUGUSTINE	VARIOUS MAINTENANCE	KCACR	1	400					1
FOLKESTONE HOLY TRINITY	INSPECTION 8 BELL CHIME	KCACR		80					
FOLKESTONE ST PETER	NEW SOLENOID TO SINGLE BELL	JT	1						1
FOLKESTONE ST SAVIOUR E	VARIOUS MAINTENANC	KCACR	1	1,000		0			
FOLKESTONE MUNDELLA SCHOOL	BELL REHUNG	KCACR	1	1,000		0		1	1
FOLKESTONE ST JOHN	INSPECTION	KCACR	1	80		0			1
FOOTS CRAY	BELLS REMOVED AND REHUNG	KCACR	1	5,000	1987	1,500	4,437	5	
	RECAST	W/C			1987				
FORDWICH	BELLS LOWERED FOR SAFETY	KCACR	1	2,000				4	

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
FRINDSBURY	BELLS REMOVED	KCACR	1	3,000	2000	2,000	3,500	8	
	REHUNG IN THE EXISTING FRAME	JT			2000				
FRINSTED	REHUNG NEW FRAME TUNED AUGMENTED TO 6	W/C	1	?	1997	3,000	5,680	5	
FRITTENDEN	VARIOUS MAINTENANCE	KCACR	1	1,000					
GILLINGHAM	VARIOUS MAINTENANCE	KCACR	1	1,000		0			
GILLINGHAM ST LUKE	INSPECTION		1						1
GODMERSHAM	BELLS REMOVED	KCACR	1	3,000	1987	1,500	4,437	5	
	BELLS REHUNG TUNED NEW FRAME AUGMENTED	W/C	1		1988				
GOODNESTONE	VARIOUS MAINTENANCE	KCACR	1	1,000				1	
GOODNESTONE BY FAVERSHAM	SINGLE BELL REHUNG	KCACR	1	1,000					1
GOUDHURST	VARIOUS MAINTENANCE	KCACR	1	2,000	1972	1,000	14,270		
GRAIN	VARIOUS MAINTENANCE	KCACR	1	1,000					
GRAVENEY	VARIOUS MAINTENANCE	KCACR	1	1,000					
GRAVESEND	VARIOUS MAINTENANCE	KCACR	1	1,000					
GREAT CHART	TENOR REMOVED FOR WELDING REHUNG	KCACR	1	3,000	2012	1,500	1,844	1	
					1960	15	352		
GREENWICH	BEARINGS CHANGED FRAME STRENGTHENED	KCACR	1	6,000					
					1955	20	553		
					2000	500	875		
HADLOW	BELLS REMOVED ASSISTANCE	KCACR	1	6,000	1994	6,000	12,329	8	
	REHUNG NEW FRAME FITTINGS TUNED	W/C							
HALLING			1		1984	500	1,703		
HARBLEDOWN ST MICHAEL	VARIOUS MAINTENANCE	KCACR	1	1,000					
HARBLEDOWN ST NICHOLAS	REMOVED AND REHUNG DEAD	KCACR	1	4,000				4	
HARRIETSHAM	VARIOUS MAINTENANCE	KCACR	1	500				2	
HARTLEY	2 BELLS REMOVED AND REHUNG SWING/C	KCACR	1	3,000					1
HARTLIP	VARIOUS MAINTENANCE		1		1975	10	85		
HAWKHURST	FORMER ALL SAINTS BELLS REMOVED	KCACR	1	2,000	1997			3	
HAWKHURST ST LAURENCE	VARIOUS MAINT.	KCACR	1	500		200			

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
	REHUNG	W/C			1966	15	293		
HAWKINGE ST MICHAEL	TRANSFERRED TO ST LUKE	KCACR	2	2,000				1	1
HAYES	VARIOUS MAINTENANCE	KCACR	1	1,000					
HEADCORN	TENOR REMOVED REHUNG RECAST 1989	KCACR	1	2,000	1992	150	325	1	
	REHUNG AND RETUNED 1981	W/C			1988	1,000	2,839	8	
					1981	500	2,166		
HERNE	BELLS REMOVED, ASSISTANCE	KCACR	1	3,000	2012	10,000	12,288		
	REHUNG IN EXISTING FRAME AUGMENTED TO 8	WHITES							
HERNE BAY	SINGLE BELL REMOVED FROM RC CHURCH	M HIGBY	1	500				1	
HERNHILL	BELLS REMOVED	KCACR	1	3,000	1997	3,000	5,680	8	
	REHUNG RETUNED EXISTING FRAME	W/C	1		1997				
HEVER	REHUNG 5/6 RECAST , ASSISTANCE		1	3,000	1995	3,500	7,024	6	
HIGH HALDEN	VARIOUS MAINTENANCE	KCACR	1	1,000				6	
HIGH HALSTOW	BELLS REMOVED REHUNG TUNED AUGMENTED	KCACR	1	7,000	1982	500	1,935		
HIGHAM ST JOHN	VARIOUS MAINTENANCE	KCACR	1	1,000					
HILBOROUGH	NEW CLAPPER FITTED TO SINGLE STEEL BELL	KCACR	1	1,000					1
HILDENBOROUGH	CLOCK BELL REMOVED FOR RECASTING	KCACR	1	500					1
HINXHILL	INSPECTION	KCACR	1	80					1
HOLLINGBORNE	BELLS AND FRAME REMOVED	KCACR	1	4,000	1975	300	2,540	8	
	BELLS REHUNG TUNED NEW FRAME AUGMENTED	KCACR		3,000	2018	3,000	3,000		
HOO ST WERBERGH	BELLS REHUNG TUNED NEW FRAME AUGMENTED	KCACR	1	3,000	1994	6,000	12,329	6	
HORSMONDEN	BELLS REMOVED ASSISTANCE	KCACR	1	4,000	1996	6,000	11,633	8	
	RETUNED REHUNG IN EXISTING FRAME	W/C			1973	70	932		
HORTON KIRBY	BELLS REMOVED TENOR REMOVED 2011	KCACR	1	5,000	2011	500	647	4	
	REHUNG NEW FRAME AUGMENTED	W/C			1999	2,000	3,552		
HOTHFIELD	VARIOUS MAINTENANCE	KCACR	1	2,000					
HOUGHAM	3 BELL CHIME MADE SERVICABLE	KCACR	1	3,000					
HUNTON	VARIOUS MAINTENANCE	KCACR	1	1,000					
HYTHE ST LEONARD	BELLS AUGMENTED LOCAL WORK	KCACR	1	10,000	1992	4,500	9,742	3	

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
	2 NEW TREBLES AND TENOR RECAST	W/C			1992				
	VARIOUS MAINTENANCE			2,000	1986	275	842		
HYTHE HOLY CROSS	VARIOUS MAINTENANCE	KCACR	1	500					1
HYTHE FORMER ST MICHAEL	VARIOUS MAINTENANCE	KCACR	1	1,000					1
HYTHE RC	SINGLE BELL REMOVED FROM RC CHURCH	KCACR	1	500				1	1
ICKHAM	BELLS REMOVED	KCACR	1	3,000				4	
	REHUNG DEAD ELLACOMBE CHIME	W/C							
IDE HILL	VARIOUS MAINTENANCE	KCACR	1	500					1
IGHTAM	VARIOUS MAINTENANCE	KCACR	1	1,000					
IVYCHURCH	VARIOUS MAINTENANCE UNRINGABLE	KCACR	1	2,000					
IWADE	2 BELLS REMOVED AND REHUNG SWING/C	KCACR	1	4,000	1992	750	1,624		1
KENARDINGTON	1 BELL REMOVED REHUNG SWING CHIMING	KCACR						1	1
KENNINGTON	REHUNG RETUNED NEW FRAME	W/C	1	?	1971	40	625		
KILNDOWN	VARIOUS MAINTENANCE	KCACR	1	1,000	1960	15	353		
KINGSDOWN	2 BELLS REHUNG SWING CHIMING	WHITES	1	0				2	1
KINGSNORTH	BELLS REMOVED	KCACR	1	3,000	1976	300	2,180	5	
	NEW FRAME BUILT LOCALLY FOR 6 BELLS	KCACR	1	6,000		?			
KINGSTON	CRACKED BELL REMOVED TO CANTERBURY	KCACR	1	1,000					1
LAMBERHURST	VARIOUS MAINTENANCE	KCACR	1	4,000		?			
LAMORBY (BEXLEY)	REPORT ON SINGLE BELL	KCACR	1	80					1
LANGLEY	VARIOUS MAINTENANCE	KCACR	1	1,000					1
LEAVELAND	INSPECTION	KCACR	1	80					1
LEEDS	VARIOUS MAINTENANCE	KCACR	1	1,000					
LEIGH			1		1979	191	1,108		
					1955	15	415		
LEWISHAM	REPORT	KCACR	1	80	1950	15	534		
LINTON	6 BELLS REMOVED	KCACR	1	3,000					
	REHUNG IN EXISTING FRAME	KCACR	1	3,000	1982	500	1,935		
LITTLE CHART	VARIOUS MAINTENANCE	KCACR	1	3,000					

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
LITTLEBOURNE	VARIOUS MAINTENANCE	KCACR	1	1,000					
LOOSE	VARIOUS MAINTENANCE	KCACR	1	1,000					
LOWER HALSTOW	VARIOUS MAINTENANCE	KCACR	1	1,000					
LOWER HARDRES	VARIOUS MAINTENANCE	KCACR	1	500					1
LYDD	VARIOUS MAINTENANCE	KCACR	1	5,000		490	490		
	REPLACING GUDGEON ON TREBLE				2015	700	790		
LYMINGE	BELLS REMOVED	KCACR	1	3,000	2002	?		8	
	REHUNG IN EXISTING FRAME, ASSISTANCE	M HIGBY	1	3,000					
					1962	10	225		
LYMPNE	BELLS REMOVED	KCACR	1	3,000	2014			8	
	REHUNG IN NEW FRAME , TUNED	W/C		3,000	1969	30	498		
	AUGMENTED TO 8	TAYLORS, KCACR	1	6,000	2015	7,000	8,093		
	4TH WELDED				2012	1,500	1,844		
LYNSTED	ADDITIONAL FRAME AUGMENT TO 6	M HIGBY, KCACR	1	5,000				1	
MAIDSTONE ALL SAINTS	REHUNG RECAST NEW FRAME	JTAYLOR	1	0	1957	600	1,019		
					2001				
	SOUNDPROOFING			0	2019	3,000	3,000		
MAIDSTONE ST MICHAEL	AUGMENTED TO 8 REHUNG RECAST OLD FRAME				1981	500	2,165		
	VARIOUS MAINTENANCE	KCACR	1	2,000	1979				
MAIDSTONE ST PAUL	TRANSFERRED TO WIGHTON NORFOLK		1		1981			1	1
MARDEN	VARIOUS MAINTENANCE	KCACR	1	3,000					
MARGATE	VARIOUS MAINTENANCE	KCACR	1	4,000	1900	40	130		
					1985				
MARGATE ST PHILLIP	REPAIR SINGLE SOLENOID BELL	KCACR	1	600					1
MEOPHAM	VARIOUS MAINTENANCE	KCACR		0	1984	250	852		
	FRAME STRENGTHED, ASSISTANCE	JTAYLOR	1	2,000	2009	?			
MEREWORTH	BELLS REMOVED	KCACR	1	3,000	2010	6,000	8,114	6	
	REHUNG TUNED EXISTING FRAME	WHITES							
MERSHAM	REHUNG NEW TIMBER FRAME TUNED	W/C	1	0	1967	25	470		

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
					1972	10	143		
MILSTEAD	REHUNG DEAD	W/C	1	0	1999				
MILTON NEXT GRAVESEND	VARIOUS MAINTENANCE	KCACR	1	2,000					
MILTON REGIS	BELLS REMOVED, ASSISTANCE	KCACR	1	4,000	2018	10,000	10,000	6	
	BELLS REHUNG/AUGMENTED EXISTING/NEW FRAME	WHITES							
MINSTER IN SHEPPEY	VARIOUS MAINTENANCE	KCACR	1	2,000					
MINSTER IN THANET	VARIOUS MAINTENANCE	KCACR	1	2,000					
MOLASH	SINGLE BELL REMOVED AND REHUNG	KCACR	1	3,000				1	1
MONKS HORTON	3 BELLS REMOVED AND PUT BACK AFTER WORK	KCACR	1	3,000				3	
MONKTON	3 NEW BELLS PLUS FRAME INSTALLED	KCACR	1	7,000	2018	10,000	10,000	3	
MURSTON	5 BELLS REMOVED FROM ROOF	KCACR	1	4,000	2013	0		5	
NACKINGTON	VARIOUS MAINTENANCE	KCACR	1	1,000	1998				1
NETTLESTEAD	BELLS REMOVED TEMP LIFTING FRAME	KCACR	1	4,000				5	
	REHUNG TUNED AUGMENTED	WC			2005	3,500	5,419		
NEW ROMNEY	BELLS REMOVED	KCACR	1	4,000	1975	?		8	
	REHUNG TUNED EXISTING FRAME	W/C							
NEWCHURCH	BELLS REMOVED	KCACR	1	3,000	1968	26	415	6	
	REHUNG NEW FRAME TUNED AUGMENTED TO 6	W/C							
NEWINGTON	BELLS REMOVED	KCACR	1	3,000	1970	15	250	6	
	REHUNG RETUNED EXISTING FRAME	TAYLOR			1970	250	677		
	3RD REMOVED REHUNG FOR WELDING	KCACR		2,000	1989				
NEWINGTON HYTHE	VARIOUS MAINTENANCE	KCACR	1	2,000					
NEWNHAM	4 BELLS REMOVED	KCACR	1	3,000	2008	6,000	8,395	6	
	REHUNG TUNED AUGMENTED TO 6	TES/KCACR		4,000	2009				
NONINGTON	INSPECTION	KCACR	1	80					
NORTH CRAY	BELLS REMOVED REHUNG DEAD	W/C, KCACR	1	4,000	1999	?		3	
NORTHBOURNE	VARIOUS MAINTENANCE	KCACR	1	2,000	1970	20	332		
NORTHFLEET	BELLS REMOVED	KCACR	1	6,000	2011	7,000	9,049	8	
	REHUNG RETUNED EXISTING FRAME	W/C, KCACR		5,000					

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
OLD ROMNEY	INSPECTION	KCACR	1	80					
ORLESTONE	VARIOUS MAINTENANCE	KCACR	1	1,000	2004	300	478		
OSPRINGE	VARIOUS MAINTENANCE	KCACR	1	2,000	2018				
OTFORD	2 BELLS REMOVED, ASSISTANCE	KCACR	1	3,000	2000			2	1
	RECAST AUGMENTED TO 6 NEW FRAME	W/C							
OTHAM	3 NEW BELLS PLUS FRAME INSTALLED	KCACR/JT	1	4,000	2012	10,000	10,000	6	
	3 ORIGINAL BELLS REHUNG EXISTING FRAME	KCACR		4,000	2018				
PATRIXBOURNE	INSPECTION, 3 BELLS	KCACR	1	80					
PEDLINGE	INSPECTION, SINGLE BELL	KCACR	1	80					1
PENGE	ADVICE	KCACR	1	0					
PENSHURST	VARIOUS MAINTENANCE	KCACR	1	3,000	1973	30	400		
PETHAM	VARIOUS MAINTENANCE	KCACR	1	4,000	1994	1,100	2,260		
PLUCKLEY	ADVICE	KCACR	1	0					
					1964	20	423		
PLUCLEY SCHOOL	ADVICE	KCACR	1	0					1
POSTLING	REHUNG DEAD 3 BELLS	W/C	1	0	1979	100	580		
PRESTON BY WINGHAM	5 BELLS IN NEW FRAME TUNED	W/C	1	0	1966	25	489	1	
	NEW TREBLE ADDED	KCACR		3,000	1983	200	200		
QUEENBOROUGH	PART REHANG	W/C	1	0	1980	250	1,278		
QUEX PARK	VARIOUS MAINTENANCE	W/C, KCACR	1	4,000				4	
RAINHAM	SOME REHUNG	JTAYLOR	1		1980	500	2,555		
					1973	50	666		
ROCHESTER CATHEDRAL	VARIOUS MAINTENANCE	KCACR	1	3,000	1992	500	1,027		
ROCHESTER ST MARGARET	8 BELLS AND FRAME REMOVED	KCACR	1	5,000	2005	3,500	5,420	8	
	REHUNG NEW FRAME TUNED	W/C		0	2006				
ROCHESTER ST NICHOLAS	3 BELLS REMOVED TO KINGSNORTH		1974	1	0			3	
RODMERSHAM	REHUNG IN EXISTING FRAME	W/C	1	0	1966				
ROLVENDEN	VARIOUS MAINTENANCE	KCACR	1	3,000	1976				
	BELLS REHUNG TUNED EXISTING FRAME	W/C			1996				

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
RUCKINGE	REHUNG IN EXISTING FRAME FITTINGS	KCACR	1	4,000	1974	66	805		
SALTWOOD	VARIOUS MAINTENANCE	KCACR	1	3,000					
	REHUNG IN EXISTING FRAME FITTINGS	W/C			1971				
ST NICHOLAS AT WADE	FRAME STRENGTHENED		1		1984	185	630	1	
SANDHURST	REHUNG NEW FITTINGS EXISTING FRAME	JT	1		1962				
	OLD 5TH WELDED RETURNED TO RING	KCACR		3,000	1989	350	948	6	
SANDWICH ST CLEMENT	NEW INSTALLATION OF 6 S/H	KCACR	1	10,000	1990	3,000	7,531		
SANDWICH ST PETER	VARIOUS MAINTENANCE	KCACR	1	1,000	2012	100	122		
SEAL	VARIOUS MAINTENANCE	KCACR/WC	1	3,000	2014	1,000	1,128		
SEAL CHART	6 BELLS REMOVED	KCACR	1	3,000	2012	10,000	10,000	6	
	REHUNG REMODELLED IN EXISTING FRAME	WHITES			1972	20	285		
SELLING	RECAST NEW FITTINGS EXISTING FRAME	W/C			1980	500	2,555		
	VARIOUS MAINTENANCE	KCACR	1	1,000					
SELLINDGE	REHUNG RETUNED EXISTING FRAME	W/C	1	0	1960	15	352		
SEVENOAKS ST LUKE	SOLENOID FITTED TO SINGLE BELL	JT	1	0	2017				1
SEVENOAKS ST NICHOLAS		W/C	1	0	1966				
SEVINGTON	STAYS SLIDERS FITTED ETC	KCACR	1	3,000	2004				
SHELDWICH	6 BROKEN BELLS AND OLD FRAME REMOVED 1997	KCACR	1	6,000	1998	3,000	8,517	6	
	NEW 8 INSTALLED	W/C			1998				
SHIPBOURNE	6 BELLS REMOVED REHUNG NOT TUNED	KCACR/WC	1	8,000	1992	3,300	7,144	6	
SHOLDEN	REHUNG CHIMING	W/C	1		1986	250	764		1
SHOREHAM	REHUNG NEW FRAME FITTINGS PLUS	W/C	1	4,000	1982	500	1,936	6	
SHORNE	VARIOUS	KCACR	1	2,000	1996				
SHORTLANDS (BROMLEY)		JT	1	0	2017				1
SIDCUP	VARIOUS MAINTENANCE	KCACR	1	2,000	1976	68	575		
	REHUNG IN EXISTING FRAME	JT			1951/74	10	345		
SITTINGBOURNE ST MICHAEL		JT	1		1979	500	2,898	8	
SITTINGBOURNE R/C	8 BELL CHIME INSTALLED	KCACR	1	4,000	2000				
	2 NEW BELLS CAST 1 AND 8	W/C							

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
SMARDEN	BELLS DISMANTLED NOT REMOVED	KCACR	1	3,000	2005	3,000	4,644		
	REHUNG IN EXISTING FRAME HAYWARD MILLS								
SMEETH	VARIOUS MAINTENANCE	KCACR	1	500					1
SNARGATE	VARIOUS MAINTENANCE, 3 BELLS	KCACR	1	1,000					
SNAVE	BELLS STOOD ON TIMBERS	KCACR	1	1,000	1978				
	CAST IN STAPLE REMOVED FROM 2ND				1982				
SNODLAND	6 BELLS REMOVED	KCACR	1	3,000	1990	2,000	5,021	6	
	REHUNG TUNED EXISTING FRAME	W/C			1990				
SOUTH ASHFORD	SINGLE BELL REHUNG DEAD	KCACR	1	3,000					1
SOUTHBOROUGH	VARIOUS MAINTENANCE		1		2005	150	232		1
SOUTHFLEET	VARIOUS MAINTENANCE	KCACR	1	2,000					
SPELDHURST	REHUNG	W/C	1	0	1986	1,000	3,059		
ST LAURENCE IN THANET	10 BELLS REMOVED	KCACR	1	3,000	1998	6,000	11,020	10	
	REHUNG TUNED EXISTING FRAME	W/C							
	2 RSJS REPLACED	KCACR		3,000					
ST NICHOLAS AT WADE	VARIOUS MAINTENANCE		1		1983	185	660		
ST PETER IN THANET	REFURB NEW GUIDES ETC JT	KCACR	1	3,000	2016	10,000	11,177		
	REHUNG TUNED EXISTING FRAME	W/C			1975	210	2,208		
STANFORD	VARIOUS MAINTENANCE	KCACR	1	1,000					1
STANSTED	3 BELLS REMOVED				1992	6,000	12,990	3	
	3 NEW BELLS TO MAKE 6 NEW FRAME TUNED	W/C							
STAPLE	4 BELLS REMOVED AND REHUNG DEAD W/C 2003	KCACR	1	4,000				4	
STAPLEHURST	8 BELLS REMOVED	KCACR	1	4,000	1996	6,000	11,633	8	
	REHUNG TUNED NEW FRAME AUG TO 10	W/C							
STELLING	VARIOUS MAINTENANCE	KCACR	1	500					
STOCKBURY	ADVICE	KCACR	1	0	2017	2,000	2,196		
STODMARSH	3 BELLS HUNG DEAD				1983	25	90		
STONE BY DARTFORD	OLD RING FROM HOMERTON INSTALLED	W/C	1		2011	4,000	5,408		
STONE IN OXNEY	VARIOUS MAINTENANCE	KCACR	1	1,000	1971	2	31		

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
STOURMOUTH	VARIOUS MAINTENANCE	KCACR	1	500					
STOWTING	VARIOUS MAINTENANCE	KCACR	1	1,000	1935	3	238		
STROOD EX ST MARY	VARIOUS MAINTENANCE	KCACR	1	500					
STROOD ST NICHOLAS	REPORT REPAIRS TO TUBULAR BELLS	KCACR	1	500					
STURRY	6 BELLS REMOVED	KCACR	1	3,000				6	
	REHUNG IN NEW FRAME TUNED	W/C			1992	6,000	12,990		
SUNDRIDGE	6 BELLS REMOVED	KCACR	1	5,000	2005	4,000	6,193	6	
	REHUNG IN EXISTING FRAME TUNED	W/C							
SUTTON BY DOVER	INSPECTION, SINGLE BELL	KCACR	1	80					1
SUTTON VALENCE SCHOOL	NEW CHAPEL MEMORIAL BELL	JTAYLOR	1	0					1
SWALECLIFFE	SINGLE BELL REMOVED FOR REFURB TBC	JTAYLOR	1	0					1
SWANSCOMBE	REHUNG BY D PAUL SMITH SOME NEW FITTINGS	DPS 1994	1	0	1997	1,000	1,893		
TEMPLE EWELL	INSPECTION		1	0					1
TEYNHAM	6 BELLS REMOVED	KCACR	1	3,000	1989	1,500	4,059	6	
	REHUNG IN EXISTING FRAME	W/C			1989				
THANINGTON	6 BELLS REMOVED	KCACR	1	3,000	1980	320	1,635	6	
	REHUNG IN EXISTING FRAME TUNED	JTAYLOR			2015	900	1,016		
THROWLEY	VARIOUS MAINTENANCE	KCACR	1	3,000	1933				
THURNHAM	VARIOUS MAINTENANCE	KCACR	1	1,000					
TUDELEY	VARIOUS MAINTENANCE	KCACR	1	1,000					
TUNBRIDGE WELLS	KING CHARLES MARTYR VARIOUS MAINTENANCE	KCACR	1	500					1
TUNBRIDGE WELLS ST PETER	VARIOUS MAINTENANCE	KCACR	1	2,000					
TUNSTALL	8 BELLS REMOVED	KCACR	1	3,000	1975	300	2,540	8	
	REHUNG TUNED IN NEW FRAME	W/C			1975			8	
	8 BELLS REMOVED	KCACR			1995				
	BELLS RECAST REHUNG IN EXISTING FRAME	JTAYLOR			1995				
TWYDALL	VARIOUS MAINTENANCE	KCACR	1	500					1
ULCOMBE	VARIOUS MAINTENANCE	KCACR	1	1,000					
WALMER ST MARY	VARIOUS MAINTENANCE	KCACR	1	4,000	2016	1,500	1,676		

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
WALTHAM	4 BELLS REMOVED	KCACR	1	3,000	2001	3,000	5,097	4	
	REHUNG TUNED AUGMENTED NEW FRAME HAYWARD MILLS								
WAREHORNE	VARIOUS MAINTENANCE	KCACR	1	1,000					
WATERINGBURY	REHUNG TUNED EXISTING FRAME	W/C	1	0	1950	10	356		
WEST FARLEIGH	INSPECTION	KCACR	1	80					
WEST MALLING		KCACR	1	3,000	1979	125	725	8	
		W/C			1960	15	352		
					1951	6	181		
	REMOVED AND REHUNG IN EXISTING FRAME				1997	3,000	5,680		
WEST PECKHAM	3 BELLS REMOVED	KCACR	1	3,000	2000			3	
	REHUNG IN EXISTING FRAME, NOT TUNED	JTAYLOR	1						
WEST WICKHAM	REHUNG AND AUGMENTED	JTAYLOR	1		1938				
WESTBERE	VARIOUS MAINTENANCE	KCACR	1	500					
WESTBROOK	VARIOUS MAINTENANCE, 1 BELL	KCACR	1	1,000				1	
WESTERHAM	REHUNG EXISTING FRAME	W/C	1	0	1971/73	20	266		
WESTGATE ON SEA	NEW INSTALLATION 6 BELLS 8 BELL FRAME	W/C	1	0	1976	260	2,202		
WESTWELL	INSPECTION	KCACR	1	80					
WHITSTABLE ALL SNTS	REHUNG TUNED NEW FRAME	W/C	1	0	1930				
WHITSTABLE ST ALPHEGE	NEW RING OF 8	W/C	1	0	1969/73	15	262		
					1974	20	244		
WICKHAMBREAUX	VARIOUS MAINTENANCE	KCACR	1	2,000					
WILLESBOROUGH	REHUNG A BOWELL		1	0	1930				
WILMINGTON	VARIOUS MAINTENANCE	KCACR	1	500					
WINGHAM	VARIOUS MAINTENANCE	KCACR	1	5,000	1990	500	1,255	1	
	WELDED SECOND BEARINGS CHANGED				2003	1,450	2,379		
WITTERSHAM	6 BELLS REHUNG AND AUGMENTED TO 8	JTAYLOR	1	0	1967/95	1,000	1,893		
WOODCHURCH	REHUNG IN EXISTING FRAME	W/C	1	0	1992	2,250	4,871		
WOOLWICH	REHUNG IN EXISTING FRAME		1	0	1932				
WORMSHILL	INSTALL 4 BELLS		1	4,000	1988	866	2,459	6	

TOWER	WORKS CARRIED OUT	WORK UNDERTAKEN BY	NO. OF CHURCHES/BUILDINGS	SAVINGS MADE USING VOLUNTARY LABOUR (AT TODAY'S PRICES)	DATE OF MAJOR WORKS	VALUE OF KCACR GRANT PAID	VALUE OF GRANT TODAY	NO > OF BELLS RAISED/LOWERED	ASSISTANCE TO 1 & 2 BELL TOWERS
				3,000	1995	1,500	3,131		
WOULDHAM	VARIOUS MAINTENANCE	KCACR	1	2,000					
WROTHAM		KCACR	1		1978	130	945		
	BELLS REHUNG EXISTING FRAME			6,000	2015	5,000	5,644		
WYCHLING	VARIOUS MAINTENANCE, 2 BELLS	KCACR	1	500					1
WYE	BELLS REHUNG, RETUNED EXISTING FRAME	W/C	1	2,000	1975	?			
	AUGMENTED TO 10	W/C		1,000	1999				
					1952	6	175		
YALDING	REHUNG NEW FRAME TUNED	W/C	1	?	1979	500	2,898		
TOTALS			343	686,840		368,090	650,962	565	57

? VALUE TO BE FOUND

SOME DATES TO BE ADDED

THE BELL RESTORATION FUND CHANGED TO A SEPARATE FUND IN 1970

BRIAN G. BUTCHER BELL RESTORATION OFFICER 2020