

## **BELL RESTORATION REPORT 2021**

A bit more activity this year but mainly inspections prior to ringing for the first time after lock down, The only major works being Faversham back in action and reports / quotes being obtained at Bethersden for rehunging.

Aldington	Inspection and maintenance.
Ash by Sandwich	Inspection and maintenance.
Ashford	Inspection and refit one clapper.
Bethersden	Various site meetings with contractors re rehunging.
Boxley	Inspection of the 5 <sup>th</sup> bell.
Chiselhurst St Nicholas	Inspection (thanks to Graham Long)
Faversham	Now ringing, with some adjustments required to sound and clock hammers.
East Langdon	Inspection and maintenance.
High Halden	Inspection, maintenance and repair to 5 <sup>th</sup> clapper.
Ightham	Clappers rebushed and refitted.
Minster in Thanet	Inspection and maintenance.
Minster in Sheppey	Inspection and maintenance.
Quex Park	Inspection and replace worn pulleys.
Sellindge	Inspection and maintenance.
Throwley	Inspection and some minor works.

Tunbridge Wells

Inspection and 7<sup>th</sup> wheel made serviceable.

Waltham

Inspection and maintenance.

Willesborough

Inspection and maintenance.

Brian G. Butcher

Bell Restoration Officer.

Diocesan Bell Adviser to Canterbury, Rochester and temporarily, Southwark